


Wirt County



Wirt County High School



Areas Patched



Aged Seams to Scupper



Tears in Roof



Screws Tearing Through Roof



Area Does Not Drain



Wirt County Middle/ Primary School




Gravel Raked Back to Find Holes



Gravel Raked Back to Find Holes



Standing Water is Growing Moss



Rubber Sealant Failing



Moisture Problems Inside Wall